

**AHERA REINSPECTION  
The Banks High School  
at  
13050 N. W. Main Street  
Banks, Oregon 97106**

**Prepared For:**

**Superintendent  
Banks School District SD 13  
12950 N.W. Main  
Banks, Oregon 97106**

**EIS Job No. 2022010. Banks High School**

**Prepared By:**

**Charles A. Spear  
AHERA Certification #IRO-21-2439A  
Environmental Inspection Services  
11981 Fargo Road  
Aurora, Oregon 97002  
(503) 680-6398  
E MAIL: [charles\\_a\\_spear@yahoo.com](mailto:charles_a_spear@yahoo.com)**

*Charles A. Spear*

---

**Charles A. Spear, Partner**

**February 3, 2022**



**EIS**  
**ENVIRONMENTAL INSPECTION SERVICES**

Bus: 503.678.5063 | Cell: 503.680.6398

11981 Fargo Road, NE, Aurora, OR 97002

[www.environmentalinspectionsservices.net](http://www.environmentalinspectionsservices.net)



## TABLE OF CONTENTS

<u>DESCRIPTION</u>	<u>PAGE NO</u>
EXECUTIVE SUMMARY.....	1-5
ACCREDITATION / RESUME.....	6-9
REGULATIONS (BACKGROUND).....	10-12
ACTIVITY (BACKGROUND).....	13
REINSPECTION REPORT.....	14
REINSPECTION SCOPE OF WORK.....	14
SUMMARY OF FRIABLE / NONFRIABLE ACBM .....	15-18
RECOMMENDATIONS AND CONCLUSIONS.....	18
LIMITATIONS.....	19

### APPENDIX 1.0

#### SITE PLAN

### APPENDIX 2.0

#### RECORDING FORMS FOR ASSESSMENT DATA

### APPENDIX 3.0

#### REGULATIONS



February 3, 2022  
EIS JOB No. 2022010.Banks High School AHERA

Superintendent  
Banks School District  
12950 N.W. Main street  
Banks, Oregon 97106

RE: Asbestos 2022 AHERA 3-year Reinspection of the Banks High School located at 13050 N.W. Main Street in Banks, Oregon

Dear Superintendent,

The Federal Asbestos Hazard Emergency Response Act (commonly referred to as AHERA) was signed into law in 1986. AHERA requires both private and public non-profit primary and secondary schools to inspect all buildings that are leased, owned, or otherwise used as school buildings for the presence of asbestos-containing building materials (ACBM). The U.S. Environmental Protection Agency (EPA) published regulations and enforces AHERA.

EIS is pleased to present the February, 2022 AHERA reinspection for The Banks High School located at 13050 N.W. Main Street in Banks, Oregon. The subject high school has been partially remodeled and renovated. Suspect asbestos-containing building materials (ACBM) includes thermal system insulation (TSI) as pipe lagging and boiler fittings in the boiler room; ceiling tile mastics; nine-inch vinyl floor tiles; moulding mastic adhesives; original ceiling tiles; pipe lagging, science lab tables, tape joint compounds, and asbestocell pipe lagging. The boiler room original TSI in the form of boiler jacket seals and damaged pipe lagging in the boiler room should be repaired. Suspect TSI debris underneath the boiler should also be sampled for asbestos content and abated as required. No other problematic conditions were observed in the school.

Conditions noted at that time included some moulding mastic damages in the custodial closet; some typical tape joint edge wear in classroom 17 and other spaces; some ceiling tile damages on ceilings of the gymnasium; exposed pipe lagging edges in the Spanish classroom and elsewhere as needed; exposed pipe lagging edges in the main shop pipe lagging; nine by nine tile in good condition with minor damage noted in classroom thresholds. Fire doors, hard fittings, pipe lagging and boiler jackets originally noted in the boiler room were in fair condition.

The subject original functional spaces were examined throughout for the presence of confirmed and suspect asbestos-containing building materials (ACBM). All representative functional spaces and relative homogeneous sampling areas were examined during the inspection process.

A total of fifteen (15) multi-data data sheets were completed for the school and noteworthy TSI wear and debris considerations and boiler damages were noted in the boiler room. Exposed asbestos-containing thermal system insulation as exposed lagging ends were noted in the main shop and Spanish classroom. Minor lagging damages should also be repaired on pipe lagging in the boiler room. Any additional exposed pipe lagging ends should be sealed as a standard repair item. The sheets summarize the accessibility and condition of identified confirmed and/or suspect asbestos-containing building materials (ACBM) observed throughout the original Banks High School building.

All identified ACBM are candidate materials for in-place operations and maintenance and asbestos abatement is not recommended or required. The condition of the existing asbestos-containing building materials is appropriate and considered to be suitable for continued use. The asbestos is managed by using proper work practices, including wet methods and proper sealing, and by using appropriate personal protective equipment (PPE) and respiratory protection. The asbestos is managed by using proper work practices, including wet methods and proper sealing, and by using appropriate personal protective equipment (PPE) and respiratory protection.

#### THERMAL SYSTEM INSULATION (TSI)

Thermal system insulation (TSI) was observed on pipe lagging on pipework in the boiler room boiler, stage room, classrooms, and main shop. Damaged TSI was observed in the boiler room, Spanish class overhead piping and main shop. TSI boiler jackets, seals, and gaskets were observed within an original boiler room on-site. Refer to sheet No.s 1,2 for details.

#### RESILIENT FLOOR COVERINGS

##### (VINYL FLOOR TILE & SHEET FLOOR LINOLEUM)

Varieties of suspect resilient floor coverings to include nine-inch olive green tile in the classrooms; nine-inch tan VAT on hallway floors; nine-inch VAT on the stage room floor; nine-inch light tan VAT on classroom floors; one-foot gray/white VAT in the hallways; nine-inch tan brown VAT on bathroom floors; and nine-inch VAT in the cafeteria were observed. No samples were collected from vinyl floor tile. Refer to data sheet No.s 3,4,6,10,11, and 14 for vinyl tile additional details.

All examined floor coverings to include nine-inch and one foot vinyl floor tiles were observed in the stairwells, hallways and classrooms and were noted in good to excellent condition, well maintained, accessible, and intact. No significant floor covering condition or damage concerns were noted. Minor damaged floor tiles may be replaced as a repair item.

#### **COVE-BASE ADHESIVE**

Cove-base mastic adhesive was observed on floor moulding within various functional spaces throughout the subject high school to include the kitchen, gymnasium, classrooms, and annex buildings. Edge wear was noted in the custodial closet and kitchen, annex room No. 24, and other minor areas in the building. The moulding is otherwise intact and in good condition. No samples were collected in moulding mastics. (Refer to data sheets No.s 8 and 15 for details.

#### **TAPE JOINT COMPOUND**

Tape joint compound was noted throughout the high school wall surfaces in areas of sheet rock joints. This compound is typically applied to taped joints applied between sheet rock wall surfaces. Tape joint compound exists on sheet rock panels throughout the subject building. The compound usage was extensive and is likely throughout the entire structure original pre-1980 wall panel tape joints. The compound is in good condition, sealed and or encapsulated, and a candidate building material for operations and maintenance. Tape joint compound was observed throughout the structure.

#### **ACOUSTIC CEILING TILES**

Nine inch square ceiling tiles were observed as the ceiling covering in the classrooms, gymnasium, shops, hallways, library, and cafeteria. Perforated ceiling tiles were observed on ceiling surfaces in the cafeteria, gymnasium, and classrooms. No samples were collected from ceiling tiles or mastics. Minor ceiling tile damages were noted on ceilings of the gymnasium. No specific ceiling tile quality concerns were noted. No problematic ceiling tiles were observed on ceiling surfaces throughout the building. (Refer to data sheet No.s 5,7,12, and 13 for details).

PLASTER (SKIM COAT)

Original wall surfaces have plaster skim coat applications observed within functional areas of the building. No samples were collected. EIS noted no plaster concerns. Refer to data sheet No. 4 for details. The wall plaster surfaces were noted to be in good condition and candidate building materials for in-place operations and maintenance. The existing plaster surfaces are sealed and coated in latex paint applications and considered to be in good condition. No concerns were noted.


All suspect and previously analytically confirmed ACBM were noted to be in good to excellent condition. All ACBM are considered candidate building materials for operations and maintenance in accordance with the standard O&M recommendations stated in The AHERA Management Plan and the EPA Manual known as Managing Asbestos in Place - A Builder Owners Guide to Operations and Maintenance Programs for Asbestos-Containing Materials per EPA Manual No. 201-2003 dated July, 1993.

During the April 2019 asbestos reinspection, the following areas were inspected: boiler room, ceiling tile storage, boiler room ceiling, and pipe lagging. No asbestos material was observed. All areas inspected were found to be in good condition.

The boiler room was inspected and found to be in good condition. All asbestos-containing materials were found to be in good condition. No asbestos-containing materials were observed in the boiler room. Damaged lag as pipe lagging and boiler seals, and suspect ACM debris were observed in the boiler room. Sampling is recommended at this time. Asbestos assessment is not recommended or necessary at this time.

Thank you for the opportunity to perform the April, 2019 asbestos reinspection. Progress has been made since the AHERA Management Plan issuance and initial inspections. The Hanks High School has been partially remodeled, relatively modern, and remaining plaster skim coats and original TSI, VAT and ceiling tile materials are well maintained and no asbestos material safety concerns were noted in the school. Minor TSI repair considerations remain in the boiler room. If there are any questions feel free to contact us at (503) 690-6398.

Respectfully,

  
Charles A. Spear  
Partner

AHFRA Inspector IRO-21-2439A

This reinspection of the Banks High School Building and outbuildings was performed on Monday, January 31, 2022 by Charles A. Spear. AHERA Inspector Certification No. IRO-2-2439A. The AHERA Inspector expiration date is February, 2022. All inspection / assessment activities were performed in accordance with the reinspection requirements of Part III 40 CFR Part 763. Asbestos-Containing Materials in Schools; Final Rule and Notice.

## RESUME

**CHARLES ARTHUR SPEAR**  
**REGISTERED ENVIRONMENTAL ASSESSOR**  
**REA - 01241**

**AHERA INSPECTOR (EPA CERTIFICATION NO. IRO-21-2439A)**

**CERTIFIED ENVIRONMENTAL INSPECTOR**  
**CEI - 10364**

### Professional Background

Charles A. Spear, President and founder of Environmental Inspection Services, has over 20 years technical experience ranging from facility food technologist to hazardous waste site remediation at Federal SUPERFUND sites from California to Maryland. Mr. Spear has successfully performed over 2,000 Phase One, Phase Two, and Phase Three Environmental Site Assessment inspections on properties from California to Alaska and east to Maryland. Mr. Spear has managed such projects as spilled mustard gas and organophosphate remediation as a sergeant of the U.S. Army Chemical Corps Technical Escort Unit Drill & Transport Unit at Fort Meade Army Depot and removal of leaking solvent underground storage tanks in California and Oregon.

Specifically, Mr. Spear has worked with clients such as the International Air & Gas Industry (IAGI), the U.S. Environmental Protection Agency, The U.S. Department of Defense, The Oregon Department of Environmental Quality (ODEQ), The Oregon Department of Forestry, INTEL, Sun Microsystems, IBM, Rohm & Haas, General Electric, AT&T, Tevaco, Unocal, BP, Lockheed Missile and Space Center, EMC Corporation, Oregon Department of Fish & Wildlife, Washington Department of Fish & Wildlife, City of Beaverton, City of Hillsboro, City of Corvallis, Housing Authority of Portland, Northwest Oregon Housing Authority, Washington County Department of Housing, Housing & Urban Development, numerous lenders and mortgage companies, many private development and site remedial site projects, and many attorneys and investors.

Mr. Spear managed complex tank farm removals at Xidex Corporation in Sunnyvale, California and was the site cleanup manager at the Rose City Plating Site currently developed as the Oregon Convention Center. Mr. Spear is a certified hazardous waste professional who has coupled military experience as a Nuclear, Biological and Chemical Specialist (U.S. Army MOS 54E20) with experience as a professional research engineer in both the corrugated paper and petroleum industries.



Mr. Spear has managed food industry quality control as an inplant food technologist and prepared cost reduction programs as a corrugated box board industrial engineer in Dallas, Texas. He is currently registered with the states of California, Washington, and Oregon and is an active member of the national respected Environmental Assessment Association. Due diligence projects have been performed throughout the United States from Fairbanks, Alaska to San Diego, California.

Professional experience includes the following:

**Professional Experience**

- \* Dry Cleaner Inspections
- \* Environmental Consultation
- \* Waste Reduction Audits
- \* Regulatory Compliance Audits
- \* Drum Yard Clearances
- \* Tank Farm Removals/Replacements
- \* Lab Packaging & Supervision
- \* Environmental Site Assessments
- \* Superfund Site Remediation
- \* Hazardous Waste site Project Design & Management
- \* Habitat/Wetlands Restoration
- \* AHERA asbestos inspections for school districts
- \* Landfill Remediation
- \* Agricultural assessments
- \* Indoor air quality inspections

**Professional Employment/Consultation**

- \* C.F.S. Continental Coffee, Inc., Food technologist, Chicago, Illinois
- \* Holiday Industries, Research Engineer, Grand Prairie, Texas
- \* Alton Packaging Corporation, Industrial Engineer, Dallas, Texas
- \* U.S. Army Chemical Corps., Nuclear, Biological, Chemical Specialist - Special assignment - Umatilla Army Depot (DATS)
- \* U.S. Army Chemical Corps. Technical Escort Unit in Edgewood, Maryland
- \* Rollins Environmental Services, Remedial Project Manager
- \* Crown Environmental Services, Technical Director, Redmond, California
- \* Dames & Moore, Design Engineer, Portland, Oregon
- \* Pegasus Environmental Management Services, Director of Technical Services
- \* Pacific Tank & Construction, Manager of Estimation, Portland, Oregon
- \* Enviro-Logic Inc., Director of Environmental Site Assessment Division
- \* Environmental Inspection Services Inc., Founder/President

### Professional Education

- \* Bachelor of Science, Chemistry, Northeastern Illinois University, 1978
- \* U.S. Army Chemical School, Ft. McClellan, Alabama, 1983
- \* U.S. Army Technical Escort Unit, Accident/Incident Response Training Center 1983
- \* Registered Environmental Assessor REA - 01241
- \* Certified Environmental Inspector CEI - 10364
- \* AHERA Certified Asbestos Inspector IRO-21-2439A
- \* ODEQ Soil Matrix Assessor & USI Decommission Supervisor
- \* Washington DOE Registered Environmental Assessor
- \* Wetland Specialist - Training Wetlands Institute 1997
- \* EPA/HUD Lead-Based Paint (LBP) Inspector & Risk Assessor
- \* ASTM Certification Training, May, 2004

### Additional Education

- \* Joint Military Material Packaging & Transportation
- \* Asbestos Abatement Seminar attendance 1987
- \* Thin Layer Chromatography, 1989
- \* Oregon Registered Underground Storage Tank Supervisor, 1998
- \* Oregon Registered Soil Matrix Assessor, 1998
- \* Washington Registered Assessor, 1991
- \* Washington Registered Underground Storage Tank Supervisor, 1991
- \* Wetland Training Institute Delineation Course Study University of Portland March 1997
- \* 40-Hour HAZMAT Certified
- \* AHERA-Certified Inspector

### Special Skills

- \* Facility Environmental Compliance Audits
- \* ASTM standard Environmental Site Assessments
- \* Computer Programming
- \* Organic surfactant chemical synthesis and analysis
- \* Hazardous Waste Site remediation/ estimating/ standards development
- \* Design of filtration systems, batch and continuous process optimization studies
- \* QA/QC Procedures
- \* SUPERFUND Site Management
- \* Industrial/ Research Engineering
- \* Hazardous Waste Site Remediation/ Consultation
- \* Wetlands Delineation and Habitat Restoration



## **Certification**

- \* U.S. Army MOS 54E20 - U.S. Army Chemical Corps.
- \* International Fire Code Institute (IFCI) Certified UST Supervisor
- \* International Fire Code Institute (IFCI) Certified Soil Matrix Assessor
- \* Certified Hazardous Waste Manager
- \* 40-hour OSHA Training
- \* 40-hour OSHA Supervisor Training
- \* Registered Environmental Assessor (DOE)
- \* DEQ Registered UST Supervisor
- \* DEQ Registered Soil Matrix Assessor
- \* Resolution Trust Corporation (RTC) approved Environmental Assessor
- \* California Registered Environmental Assessor (REA-01241)
- \* Department of Ecology (DOE) Registered Environmental Assessor
- \* Environmental Assessment Association, Certified Environmental Inspector & Transaction Specialist (CEI-10364)
- \* AHERA Certified Asbestos Inspector
- \* Wetland Delineator Graduate Wetland Training Institute, University of Portland 1997
- \* EPA/HUD/EBP Inspector & Risk Assessor
- \* ASTM certification

## REGULATIONS

### Asbestos - Background

Asbestos is generally referred to as six naturally occurring fibrous minerals found in certain types of rock formations. The minerals Chrysotile, Amosite, and Crocidolite have been most commonly utilized in building materials. Asbestos is typically separated into very thin fibers. Asbestos is strong, incombustible, and corrosion resistant and was utilized early in the century into the 1970's. Asbestos may cause substantial health problems when it is inhaled in sufficient quantities.

Asbestos is considered to be a hazardous air contaminant and a known human carcinogen. Once used extensively as an insulation material, asbestos has been banned from most construction and manufacturing since the mid-1970's. The most dangerous forms of asbestos are those materials containing asbestos which can be easily crushed or crumbled known as "friable asbestos". Friable asbestos is dangerous since asbestos fibers can be easily released into the air. Such activities as remodeling and demolition projects are likely to disturb asbestos. If asbestos-containing building materials (ACBM) are not handled properly then these types of projects can pose as a serious threat to workers and the general public.

### Regulatory Background

In 1986, Congress enacted the Asbestos Hazard Emergency Response Act (AHERA or TSCA Title II) which mandated a regulatory program to address asbestos hazards in schools. A copy of the Environmental Protection Agency Asbestos Model Accreditation Plan interim Final Rule (59FR2236-5260) is enclosed for reference. President Reagan signed into law the Asbestos Hazard Emergency Response Act (AHERA) on October 22, 1986. This law enacted, among other provisions, Title 2 of the Toxic Substances control Act (TSCA) 15 U.S.C. Section 2641 through 2654; Section 203 of Title II, 15 U.S.C. 2643. Copies of AHERA 40 CFR Part 763 are enclosed for reference.

**AHERA requires the following:**

- (1.0) - Perform an original inspection and periodic re-inspections every three years for asbestos containing material;
- (2.0) - Develop, maintain, and update an asbestos management plan. A copy must be kept in the school building, as well as in the district's administrative office;
- (3.0) - Provide an annual written notification to parent, teacher, and employee organizations regarding the availability of the school's asbestos management plan for review and any asbestos abatement actions taken or planned in the school;
- (4.0) - Designate a contact person (also known as the asbestos designee) to ensure the responsibilities of the local education agency are properly implemented. Details on the asbestos designee's responsibilities can be found at: [www.epa.gov/asbestos](http://www.epa.gov/asbestos).
- (5.0) - Establish a procedure to ensure that all asbestos-containing materials (ACM) are properly managed, including:
- (5.1) - Identification of ACM;
- (5.2) - Assessment of ACM;
- (5.3) - Management of ACM;
- (5.4) - Abatement of ACM;
- (5.5) - Recordkeeping.

When a building has never been inspected for asbestos, a new AHERA inspection must be completed as soon as possible. Pursuant to AHERA Section 763.85(a), any building leased or acquired on or after October 12, 1988, that is used as a school building shall be inspected for asbestos prior to use as a school building. In the event that the emergency use of an uninspected building as a school building is necessitated, such building must be inspected for asbestos within 30 days after the commencement of such use.

Section 112 of the Clean Air Act (CAA) requires EPA to develop emission standards for hazardous air pollutants. In response to this section the EPA published a list of hazardous air pollutants and promulgated the National Emission Standards for Hazardous Air Pollutants (NESHAP) regulations.

The asbestos NESHAP (40 CFR 61, Subpart M) addresses milling, manufacturing and fabricating operations, demolition, and renovation activities, waste disposal issues, active and inactive waste disposal sites and asbestos conversion processes.

In the initial Asbestos NESHAP rule promulgated in 1973, a distinction was made between building materials that would readily release asbestos fibers when damaged or disturbed and those materials that were unlikely to result in significant fiber release. The terms "friable and non-friable" were used to make this distinction. EPA has since determined that, if severely damaged, or otherwise non-friable materials can release significant amounts of asbestos fibers.

Friable asbestos-containing material (ACM) is defined by the Asbestos NESHAP as any material containing more than one percent (1%) asbestos as determined using the method specified in Appendix A, Subpart F, 40 CFR Part 763, Section 1, Polarized Light Microscopy (PLM), that when dry, can be crumbled, pulverized, or reduced to powder by hand pressure (section 61.141). Non-friable material is ACM not reduced to powder by similar circumstances.

**ACTIVITY**

Background

It is the responsibility and primary mission of the AHERA inspector to determine whether ACM is present in a building and to assess the physical characteristics of the ACM in the structure. The inspection process includes an investigation of available records; an inspection of the functional spaces; an assessment of the condition of observed ACM; reviews of available architectural and as built plans; review of work change orders; examination of material specifications indicating the presence of ACM; examination of friable and non-friable ACM; delineation of homogeneous sample areas; collection of samples; and information on ACM conditions.

The Banks High School gymnasium, boiler room, kitchen, cafeteria, classrooms, library, offices, galleries, vestibules, and hallways were examined for suspect ACM during the AHERA reinspection. Data forms were completed. The completed forms were returned to the AHERA inspector who will determine if any further action is required. If any further action is required, the AHERA inspector will determine the type of action and when it should be completed. If any further action is required, the AHERA inspector will determine the type of action and when it should be completed.



## **REINSPECTION**

Charles A. Spear conducted a triennial asbestos reinspection of the Banks High School building on Monday, January 31, 2022. Actual field activities included blueprint and/or facility floor plan review; an interview with the maintenance supervisor; and a physical reinspection examination of all suspect and confirmed friable and non-friable asbestos-containing building materials at the subject Banks school. The Banks School hallways, common rooms, and class rooms wall, floor and ceiling surfaces are well maintained.

The accredited EIS inspector performed a preliminary examination of the subject structure. The AHERA inspector confirmed the existence of suspect asbestos-containing building materials (ACBM) such as thermal system insulation (TSI); vinyl asbestos floor tiles; moulding mastic adhesives; skim coat plaster applications on sheet rock; science room table surfaces, and acoustic ceiling tiles ceiling tile adhesives, and miscellaneous and cementitious materials.

All accessible areas to include The Banks School gymnasium, hallways, classrooms, cafeteria, boiler room, girls and boys locker rooms, original kitchen, shops, science room, galleries, vestibules, and storage rooms and stairwells were examined for suspect ACBM during the AHERA reinspection. All the aforementioned functional areas were visibly inspected during this AHERA reinspection. No significantly damaged ACBM was observed during these inspections. Some minor TSI damages were observed in the boiler room.

The Banks High School Building walkover revealed all asbestos-containing materials to be candidate building materials for Operations and Maintenance. The original AHERA Management Plan confirmed asbestos in several forms. Operations and Maintenance is recommended for all confirmed and suspected asbestos-containing materials to include pipe lagging TSI; boiler jacket TSI; vinyl asbestos tiles (VAT); ceiling tiles; and miscellaneous materials. No ACBM concerns were noted for the aforementioned materials. Asbestos abatement is not recommended for the subject facility ACBM at this time. Minor repair of damaged areas is adequate and protective.

All the aforementioned materials are in good condition and candidate materials for Operations and Maintenance. No noteworthy damages or disturbances of ACBM were observed. These materials have low potential for damage with no influence of vibration or potential for air erosion.

## SUMMARY OF FRIABLE / NONFRIABLE ACBM

Staff and maintenance personnel are encouraged to consult the forms prior to maintenance activities planned for suspect ACBM.

### 1.0 Vinyl Asbestos Tile (VAT) Non-Friable

Varieties of suspect resilient floor coverings to include nine-inch olive green tile in the classrooms, nine-inch VAT on the stage roof floor; nine-inch light tan VAT in the classrooms; one-foot gray/white VAT in the hallways;; nine-inch tan brown VAT on bathroom floors; and nine-inch VAT and one foot in the cafeteria were observed. No samples were collected from vinyl floor tile. (Refer to datasheet No.s 3,4,6,10, and 14 for details).

Description - a nonfriable vinyl material with vinyl filler and binder. An adhesive mastic is utilized to adhere to the vinyl floor surfacing to another substrate. The VAT asbestos content is described as a separate matrix from the adhesive mastic. VAT suspect to contain asbestos was identified when plastic covering the floor was removed and the floor was inspected. The VAT suspect to contain asbestos was identified when the floor was removed and the floor was inspected. The VAT suspect to contain asbestos was identified when the floor was removed and the floor was inspected.

AHERA Classification-Miscellaneous

### COVE-BASE ADHESIVE

The cove base adhesive was identified in the kitchen, gymnasium, classrooms, and annex buildings. Edge wear was noted in the kitchen, annex room No. 14, and other minor areas in the building. The moulding is otherwise intact and in good condition. No samples were collected in moulding mastic. No samples were collected in moulding mastic. (Refer to data sheets No.s 8 and 15 for details).

### TAPE JOINT COMPOUND

Tape joint compound was noted throughout the high school wall surfaces in areas of sheet rock joints. This compound is typically applied to taped joints applied between sheet rock wall surfaces. Tape joint compound exists on sheet rock panels throughout the subject building. The compound usage was extensive and is likely throughout the entire structure original pre-1980 wall panel tape joints. The compound is in good condition, sealed and or encapsulated, and a candidate building material for operations and maintenance.

Products not utilized as TSI or surfacing materials are classified as miscellaneous materials. Materials such as transite pipe, ceiling tiles, fire doors, gaskets, vinyl floor coverings, duct work flexible connections, roofing felt, roofing flashing, and fume hood ducting and paneling are miscellaneous materials.

These miscellaneous materials were noted in various areas of the subject building as noted in data sheets. Samples were not collected from suspect ACBM.

ACM sprayed or troweled onto surfaces for acoustical, decorative, or fireproofing purposes. Asbestos is blended in to spray-applied and troweled-on products to include structural fireproofing, stucco, plaster, acoustical and decorative surfaces, and joint compounds.

## **2.0 Thermal System Insulation (TSI)**

AHERA Classification - TSI

Thermal system insulation (TSI) was observed on pipe lagging on piperuns in the stage room, classrooms, and main shop. Damaged TSI was observed in the Spanish class overhead piping and main shop. Damaged TSI boiler jackets, seals, pipe lagging, and gaskets were observed within a boiler room on-site.

Insulation used on mechanical systems to prevent heat ,loss or gain and condensation. Steam and hot water lines, boiler tanks, expansion joints, fittings and other mechanical systems are commonly insulated with pre-fabricated asbestos-containing magnesium silicate. The material is typically white in color and is encased in a plaster-impregnated canvas wrapping. Asbestos containing mud compounds are often used on elbows, valves, identification plates, miscellaneous fittings, and for other special applications on mechanical systems. Some Pipe run TSI has been abated. (Refer to datasheet No.s 1 and 2 for details.

### 3.0 Acoustic ceiling Tiles, Suspect - Non Friable Miscellaneous

Nine inch square ceiling tiles were observed as the ceiling covering in the classrooms, gymnasium, shops, hallways, library, and cafeteria. Perforated ceiling tiles were observed on ceiling surfaces in the gymnasium, and classrooms. No samples were collected from ceiling tiles or mastics. No specific ceiling tile quality concerns were noted. No problematic ceiling tiles were observed on ceiling surfaces throughout the building.

No problematic ceiling tiles were observed on ceiling surfaces throughout the building. (Refer to datasheet No.s 5,7,12, and 13 for details).

Fibrous acoustical ceiling tiles, varying in size from one foot square to two by four foot lengths. Fibrous material integrated with cellulose binder and directly adhered to ceiling surfaces. The material in most classrooms is in good condition. Ceiling tiles are easily damaged and may create a dust hazard if the material is broken, abraded, cut, or drilled. Acoustical ceiling tiles were observed on ceiling surfaces in the classrooms. The primary concern is that the material is easily damaged and may create a dust hazard if the material is broken, abraded, cut, or drilled. The material is otherwise in good condition.

### 4.0 Adhesive mastic

Adhesive mastic was observed in the classrooms, gymnasium, shops, hallways, library, and cafeteria. The mastic is otherwise in good condition. No samples were collected in mastic. (Refer to data sheet No.s 8 and 15 for details).

Typical to adhere ceiling acoustic panels to underlying substrate. Material is non-problematic and non-friable.

ACM sprayed or troweled onto surfaces for acoustical, decorative, or fireproofing purposes. Asbestos is blended in to spray-applied and troweled-on products to include structural fireproofing, stucco, plaster, acoustical and decorative surfaces, and joint compounds.

### (5.0) - Sprayed-on acoustic popcorn ceiling materials

No suspect popcorn ceiling materials were observed within the subject building. Popcorn ceiling materials are an acoustic sprayed-on application spray applied to ceiling sheet rock surfaces as an acoustic material.

## **RECOMMENDATIONS AND CONCLUSIONS**

All thermal system insulation (TSI) piperuns, boiler jacket TSI materials; vinyl asbestos tiles flooring materials; acoustic ceiling tiles; ceiling tile mastics; and miscellaneous skim coat plaster applications on sheet rock wall panels materials are candidate building materials for Operations and Maintenance. Asbestos abatement of confirmed asbestos-containing building materials is not recommended at this time. EIS noted no concerns other than minor repair items in the boiler room pipe lagging, boiler jacket seals, and suspect TSI debris under the boiler.

In all areas where work or work-related activities are planned materials must be properly tested and classified as non-asbestos. If confirmed, all asbestos containing building materials must be handled, managed, or removed in accordance with state and federal regulations. Asbestos abatement is not recommended or required at this time. No environmental concerns regarding ACBM at the Banks School were noted at this time.

All confirmed ACBM scheduled for material damage or disturbance by renovation, remodeling, or demolition must be properly abated in accordance with EPA and ODEQ recommendations and procedures.

All maintenance workers and related staff must handle ACBM in accordance with the protective provisions of the Oregon Occupational Safety and Health Administration (OSHA) requirements. Maintenance and staff personnel are encouraged to follow the management recommendations of the AHERA management plan and related operations and maintenance procedures as outlined in the appendix of this letter.

## LIMITATIONS

This report was prepared in accordance with generally accepted AHERA standards of environmental reinspection practice at the time this investigation was performed. Evaluations of the conditions at the site for the purpose of this investigation are made from a limited number of observation points and may be subjective in some cases. The subject school district is solely responsible for providing any notices or disclosures to concerned public agencies or to the public.

Environmental Inspection Services has prepared this report based on information collected from available records and files. The scope of this investigation is limited and did not include subsurface exploration or chemical screening of soil and groundwater beneath the site. No bulk material samples were collected from the subject school suspect ACBM for the purposes of this reinspection.

The findings and conclusions are not to be regarded as scientific certainties. Findings are based on professional judgment and may vary depending on the information available. Evaluation of the site conditions is based on the information available at the time of the investigation. The findings and conclusions are based on the information available at the time of the investigation. The findings and conclusions are based on the information available at the time of the investigation.

**APPENDIX 1.0**

**SITE PLAN**

APPENDIX 2.0

RECORDING FORMS FOR ASSESSMENT DATA



RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Dault's Hls FLOOR MAN  
FUNCTIONAL AREA Boiler rm HOMOGENEOUS MATERIAL Boiler Jacket

TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI X  
FLOORING \_\_\_\_\_ CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
DESCRIPTION OF MATERIAL \_\_\_\_\_

APPROXIMATE AMOUNT OF MATERIAL (SF) 716 (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI X MISC \_\_\_\_\_ FLOOR \_\_\_\_\_ CEILING \_\_\_\_\_

DESCRIPTION

APPROXIMATE AMOUNT OF MATERIAL \_\_\_\_\_ (SF) 716 (LF) \_\_\_\_\_

FRIABLE: \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_  
NON-FRIABLE \_\_\_\_\_ (YES) X (NO) \_\_\_\_\_  
WARNING LABELS \_\_\_\_\_ (YES) X (NO) \_\_\_\_\_  
CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL X WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED X  
PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% X 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_

①  
②

OVERALL RATING: GOOD X FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
DESCRIPTION: See jacket wear req patch  
See John

POTENTIAL FOR DISTURBANCE: ACCESSIBLE \_\_\_\_\_ INACCESSIBLE \_\_\_\_\_  
POTENTIAL FOR CONTACT: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE X LOW \_\_\_\_\_  
INFLUENCE OF VIBRATION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE X LOW \_\_\_\_\_  
POTENTIAL FOR AIR EROSION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE X LOW \_\_\_\_\_  
OVERALL RATING: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE X LOW \_\_\_\_\_

DESCRIPTION: Candidate for in-place operations and maintenance  
LOCATION IN AIR PLENUM: YES X NO \_\_\_\_\_  
Operations and Maintenance repair of boiler jacket/seal

INSPECTOR: Charles Spear ACCREDITATION NO. 100-21-24394  
SIGNATURE: Charles Spear DATE: 11/31/22

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Banks H/G FLOOR 11A N  
FUNCTIONAL AREA Boiler HOMOGENEOUS MATERIAL Pipe Lagging

TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI X  
FLOORING \_\_\_\_\_ CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
DESCRIPTION OF MATERIAL \_\_\_\_\_

APPROXIMATE AMOUNT OF MATERIAL (SF) 7 (LF) 2100

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI 7 MISC \_\_\_\_\_ FLOOR \_\_\_\_\_ CEILING \_\_\_\_\_

DESCRIPTION

APPROXIMATE AMOUNT OF MATERIAL \_\_\_\_\_ (SF) \_\_\_\_\_ (LF) \_\_\_\_\_

FRIABLE: \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_  
NON-FRIABLE \_\_\_\_\_ (YES) 0 (NO) \_\_\_\_\_  
WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_  
CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL \_\_\_\_\_ WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED 0  
PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% 7 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
OVERALL RATING: GOOD X FAIR \_\_\_\_\_ POOR \_\_\_\_\_

DESCRIPTION: water  
open

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE \_\_\_\_\_  
POTENTIAL FOR CONTACT: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X  
INFLUENCE OF VIBRATION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X  
POTENTIAL FOR AIR EROSION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X  
OVERALL RATING: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW \_\_\_\_\_

DESCRIPTION: Candidate for in-place operations and maintenance  
LOCATION IN AIR PLENUM: YES \_\_\_\_\_ NO \_\_\_\_\_  
Operations and Maintenance 044

INSPECTOR: Charles Spear ACCREDITATION NO. FD0-21-2489A  
SIGNATURE: Charles Spear DATE: 1/31/22 ms

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Banks H/A FLOOR 1st  
FUNCTIONAL AREA class HOMOGENEOUS MATERIAL 9" tan VBT

TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
FLOORING  CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
DESCRIPTION OF MATERIAL 9" tan VBT

APPROXIMATE AMOUNT OF MATERIAL (SF) 2164 (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR  CEILING \_\_\_\_\_

DESCRIPTION 9" tan tile

APPROXIMATE AMOUNT OF MATERIAL (SF) 1164 (LF) \_\_\_\_\_

FRIABLE: (YES) \_\_\_\_\_ (NO) \_\_\_\_\_  
NON-FRIABLE (YES)  (NO) \_\_\_\_\_  
WARNING LABELS (YES) \_\_\_\_\_ (NO)   
CHANGE FROM INITIAL AHERA REPORT (YES) \_\_\_\_\_ (NO)

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL  WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED   
PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10%  10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
OVERALL RATING: GOOD  FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
DESCRIPTION: 094

POTENTIAL FOR DISTURBANCE: ACCESSIBLE  INACCESSIBLE \_\_\_\_\_  
POTENTIAL FOR CONTACT: HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW   
INFLUENCE OF VIBRATION: HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW   
POTENTIAL FOR AIR EROSION: HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW   
OVERALL RATING: HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW

DESCRIPTION: Candidate for in-place operations and maintenance  
LOCATION IN AIR PLENUM: YES \_\_\_\_\_ NO \_\_\_\_\_  
Operations and Maintenance 094

INSPECTOR: Charles Spear ACCREDITATION NO. #10-21-2435A  
SIGNATURE: Charles Spear DATE: 1/21/22

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING balls Hqs FLOOR 11A W  
FUNCTIONAL AREA balls HOMOGENEOUS MATERIAL 9" tan hls

TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
FLOORING  CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
DESCRIPTION OF MATERIAL 9" tan VAT

APPROXIMATE AMOUNT OF MATERIAL (SF) 71010 (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR  CEILING \_\_\_\_\_

DESCRIPTION 9" tan hls

APPROXIMATE AMOUNT OF MATERIAL \_\_\_\_\_ (SF) \_\_\_\_\_ (LF) \_\_\_\_\_

FRIABLE: \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_  
NON-FRIABLE \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_  
WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_  
CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL \_\_\_\_\_ WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED   
PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10%  10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
OVERALL RATING: GOOD  FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
DESCRIPTION: CM

POTENTIAL FOR DISTURBANCE: ACCESSIBLE  INACCESSIBLE \_\_\_\_\_  
POTENTIAL FOR CONTACT: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW   
INFLUENCE OF VIBRATION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW   
POTENTIAL FOR AIR EROSION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW   
OVERALL RATING: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW

DESCRIPTION: Candidate for in-place operations and maintenance  
LOCATION IN AIR PLENUM: YES  NO \_\_\_\_\_  
Operations and Maintenance CM

INSPECTOR: Charles Spear ACCREDITATION NO. FAD-21-2439A  
SIGNATURE: Charles Spear DATE: 11/21/22

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING B-1/S H/2 FLOOR 4th  
FUNCTIONAL AREA Gym HOMOGENEOUS MATERIAL 9" ac tiles  
TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
FLOORING \_\_\_\_\_ CEILING ✓ WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
DESCRIPTION OF MATERIAL \_\_\_\_\_

APPROXIMATE AMOUNT OF MATERIAL (SF) 7100 (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR \_\_\_\_\_ CEILING ✓

DESCRIPTION 9" acoustic ceiling tiles

APPROXIMATE AMOUNT OF MATERIAL (SF) 7100 (LF) \_\_\_\_\_

FRIABLE: \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_  
NON-FRIABLE \_\_\_\_\_ (YES) ✓ (NO) \_\_\_\_\_  
WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) ✓  
CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) ✓

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL ✓ WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED ✓  
PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% ✓ 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
OVERALL RATING: GOOD ✓ FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
DESCRIPTION: mbd

POTENTIAL FOR DISTURBANCE: ACCESSIBLE ✓ INACCESSIBLE \_\_\_\_\_  
POTENTIAL FOR CONTACT: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW ✓  
INFLUENCE OF VIBRATION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW ✓  
POTENTIAL FOR AIR EROSION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW ✓  
OVERALL RATING: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW ✓

DESCRIPTION: Candidate for in-place operations and maintenance  
LOCATION IN AIR PLENUM: YES ✓ NO \_\_\_\_\_  
Operations and Maintenance \_\_\_\_\_

INSPECTOR: Charles Spear ACCREDITATION NO. 100-21-24391  
SIGNATURE: Charles Spear DATE: 1/31/22

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Bulls H/s FLOOR WPHW  
 FUNCTIONAL AREA clean HOMOGENEOUS MATERIAL 9" green mat floor / 9" red  
 TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
 FLOORING X CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
 DESCRIPTION OF MATERIAL \_\_\_\_\_

APPROXIMATE AMOUNT OF MATERIAL (SF) 2124 (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR X CEILING \_\_\_\_\_

DESCRIPTION

APPROXIMATE AMOUNT OF MATERIAL \_\_\_\_\_ (SF) \_\_\_\_\_ (LF) \_\_\_\_\_

FRIABLE: \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_

NON-FRIABLE \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_

WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_

CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL X WATER \_\_\_\_\_ FIRE \_\_\_\_\_

EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED X

PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% \_\_\_\_\_ X 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_

OVERALL RATING: GOOD X FAIR \_\_\_\_\_ POOR \_\_\_\_\_

DESCRIPTION: OPM

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE \_\_\_\_\_

POTENTIAL FOR CONTACT: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE X LOW \_\_\_\_\_

INFLUENCE OF VIBRATION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE X LOW \_\_\_\_\_

POTENTIAL FOR AIR EROSION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE X LOW \_\_\_\_\_

OVERALL RATING: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE X LOW \_\_\_\_\_

DESCRIPTION: Candidate for in-place operations and maintenance

LOCATION IN AIR PLENUM: YES \_\_\_\_\_ NO \_\_\_\_\_

Operations and Maintenance OPM

INSPECTOR: Charles Spear ACCREDITATION NO. 200-21-2439A

SIGNATURE: [Signature] DATE: 1/21/2000

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Balls - H/S. FLOOR MAN  
FUNCTIONAL AREA Vocational room HOMOGENEOUS MATERIAL ceiling tiles

TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
FLOORING \_\_\_\_\_ CEILING X WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
DESCRIPTION OF MATERIAL Plg 2

APPROXIMATE AMOUNT OF MATERIAL (SF) 1168 (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR \_\_\_\_\_ CEILING X

DESCRIPTION

APPROXIMATE AMOUNT OF MATERIAL \_\_\_\_\_ (SF) 1168 (LF) \_\_\_\_\_

FRIABLE: \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_

NON-FRIABLE \_\_\_\_\_ (YES) X (NO) \_\_\_\_\_

WARNING LABELS (YES) \_\_\_\_\_ (NO) X

CHANGE FROM INITIAL AHERA REPORT (YES) \_\_\_\_\_ (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL X WATER \_\_\_\_\_ FIRE \_\_\_\_\_

EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED X

PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% X 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_

OVERALL RATING: GOOD 6 FAIR \_\_\_\_\_ POOR \_\_\_\_\_

DESCRIPTION: 6 ft

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE \_\_\_\_\_

POTENTIAL FOR CONTACT: HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X

INFLUENCE OF VIBRATION: HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X

POTENTIAL FOR AIR EROSION: HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X

OVERALL RATING: HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X

DESCRIPTION: Candidate for in-place operations and maintenance

LOCATION IN AIR PLENUM: YES \_\_\_\_\_ NO \_\_\_\_\_

Operations and Maintenance of m

INSPECTOR: Charles Spear ACCREDITATION NO. IAO-21-2499A

SIGNATURE: Charles Spear DATE: 11/31/22 -wr

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Banks FLOOR upflr  
FUNCTIONAL AREA Veranda HOMOGENEOUS MATERIAL modern mastic

TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
FLOORING \_\_\_\_\_ CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER X  
DESCRIPTION OF MATERIAL modern mastic

APPROXIMATE AMOUNT OF MATERIAL (SF) 510 + (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC X FLOOR \_\_\_\_\_ CEILING \_\_\_\_\_

DESCRIPTION

APPROXIMATE AMOUNT OF MATERIAL \_\_\_\_\_ (SF) \_\_\_\_\_ (LF) \_\_\_\_\_

FRIABLE: \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_

NON-FRIABLE \_\_\_\_\_ (YES) X (NO) \_\_\_\_\_

WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) X

CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL \_\_\_\_\_ WATER \_\_\_\_\_ FIRE \_\_\_\_\_

EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED X

PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% X 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_

OVERALL RATING: GOOD X FAIR \_\_\_\_\_ POOR \_\_\_\_\_

DESCRIPTION: CAH

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE \_\_\_\_\_

POTENTIAL FOR CONTACT: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X

INFLUENCE OF VIBRATION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X

POTENTIAL FOR AIR EROSION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X

OVERALL RATING: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X

DESCRIPTION: Candidate for in-place operations and maintenance

LOCATION IN AIR PLENUM: YES X NO \_\_\_\_\_

Operations and Maintenance CAH

INSPECTOR: Charles Spear ACCREDITATION NO. JAD-21-24592

SIGNATURE: Charles Spear DATE: 1/31/22



RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Bldg FLOOR NAN  
FUNCTIONAL AREA Vocational HOMOGENEOUS MATERIAL plaster/texture  
wall  
TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
FLOORING \_\_\_\_\_ CEILING \_\_\_\_\_ WALLS X OTHER \_\_\_\_\_  
DESCRIPTION OF MATERIAL texture

APPROXIMATE AMOUNT OF MATERIAL (SF) 71012 (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC X FLOOR \_\_\_\_\_ CEILING \_\_\_\_\_

DESCRIPTION

texture/plaster-sheetrock  
APPROXIMATE AMOUNT OF MATERIAL \_\_\_\_\_ (SF) 71012 (LF) \_\_\_\_\_  
FRIABLE: \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_  
NON-FRIABLE \_\_\_\_\_ (YES) X (NO) \_\_\_\_\_  
WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) X  
CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL X WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED X  
PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% X 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
OVERALL RATING: GOOD X FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
DESCRIPTION: intact

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE \_\_\_\_\_  
POTENTIAL FOR CONTACT: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X  
INFLUENCE OF VIBRATION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X  
POTENTIAL FOR AIR EROSION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X  
OVERALL RATING: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X

DESCRIPTION: Candidate for in-place operations and maintenance  
LOCATION IN AIR PLENUM: YES X NO \_\_\_\_\_  
Operations and Maintenance OPW

INSPECTOR: Charles Spear ACCREDITATION NO. FR0-21-2459A  
SIGNATURE: Charles Spear DATE: 11/31/22

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Bullock Vocational FLOOR main  
FUNCTIONAL AREA halls HOMOGENEOUS MATERIAL tile

TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
FLOORING x CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
DESCRIPTION OF MATERIAL \_\_\_\_\_

APPROXIMATE AMOUNT OF MATERIAL (SF) 124 (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR ✓ CEILING \_\_\_\_\_

DESCRIPTION

APPROXIMATE AMOUNT OF MATERIAL \_\_\_\_\_ (SF) ✓ (LF) \_\_\_\_\_

FRIABLE: \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_  
NON-FRIABLE \_\_\_\_\_ (YES) ✓ (NO) \_\_\_\_\_  
WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) ✓  
CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL ✓ WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED ✓  
PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% x 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
OVERALL RATING: GOOD ✓ FAIR \_\_\_\_\_ POOR \_\_\_\_\_

DESCRIPTION: \_\_\_\_\_

POTENTIAL FOR DISTURBANCE: ACCESSIBLE \_\_\_\_\_ INACCESSIBLE \_\_\_\_\_  
POTENTIAL FOR CONTACT: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW ✓  
INFLUENCE OF VIBRATION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW \_\_\_\_\_  
POTENTIAL FOR AIR EROSION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW \_\_\_\_\_  
OVERALL RATING: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW \_\_\_\_\_

DESCRIPTION: Candidate for in-place operations and maintenance  
LOCATION IN AIR PLENUM: YES \_\_\_\_\_ NO \_\_\_\_\_  
Operations and Maintenance Open

INSPECTOR: Charles Spear ACCREDITATION NO. IM-21-2435A  
SIGNATURE: Charles Spear DATE: 1/31/20

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Dredge H/S FLOOR main  
FUNCTIONAL AREA Halls HOMOGENEOUS MATERIAL 9" tan pattern tiles

TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
FLOORING X CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
DESCRIPTION OF MATERIAL 9" tiles

APPROXIMATE AMOUNT OF MATERIAL (SF) 710 (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR X CEILING \_\_\_\_\_

DESCRIPTION 9" tan pattern vinyl asbestos tiles

APPROXIMATE AMOUNT OF MATERIAL (SF) 710 (LF) \_\_\_\_\_

FRIABLE: \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_  
NON-FRIABLE \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_  
WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) X  
CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL X WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED \_\_\_\_\_  
PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% X 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
OVERALL RATING: GOOD X FAIR \_\_\_\_\_ POOR \_\_\_\_\_

DESCRIPTION: \_\_\_\_\_

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE \_\_\_\_\_  
POTENTIAL FOR CONTACT: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE X LOW \_\_\_\_\_  
INFLUENCE OF VIBRATION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE X LOW \_\_\_\_\_  
POTENTIAL FOR AIR EROSION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE X LOW \_\_\_\_\_  
OVERALL RATING: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE X LOW \_\_\_\_\_

DESCRIPTION: Candidate for in-place operations and maintenance  
LOCATION IN AIR PLENUM: YES \_\_\_\_\_ NO \_\_\_\_\_  
Operations and Maintenance \_\_\_\_\_

INSPECTOR: Charles Spear ACCREDITATION NO. IP0-21-24391  
SIGNATURE: Charles Spear DATE: 1/3/22 - mm

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Proles Hl FLOOR Mus  
FUNCTIONAL AREA light table HOMOGENEOUS MATERIAL tile/mant

TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
FLOORING \_\_\_\_\_ CEILING X WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
DESCRIPTION OF MATERIAL 9" ceiling tiles

APPROXIMATE AMOUNT OF MATERIAL (SF) 7100 (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR \_\_\_\_\_ CEILING X

DESCRIPTION 9" ceiling tiles

APPROXIMATE AMOUNT OF MATERIAL (SF) 7100 (LF) \_\_\_\_\_

FRIABLE: \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_  
NON-FRIABLE \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_  
WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_  
CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL X WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED X  
PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% \_\_\_\_\_ X 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
OVERALL RATING: GOOD X FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
DESCRIPTION: Open

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE \_\_\_\_\_  
POTENTIAL FOR CONTACT: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X  
INFLUENCE OF VIBRATION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X  
POTENTIAL FOR AIR EROSION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X  
OVERALL RATING: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X

DESCRIPTION: Candidate for in-place operations and maintenance  
LOCATION IN AIR PLENUM: YES X NO \_\_\_\_\_  
Operations and Maintenance OPM

INSPECTOR: Charles Spear ACCREDITATION NO. 100-21-2439A  
SIGNATURE: Charles Spear DATE: 1/31/02

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Banks, H/S FLOOR MAIN  
FUNCTIONAL AREA #26 HOMOGENEOUS MATERIAL Asbestos

TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
FLOORING \_\_\_\_\_ CEILING  WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
DESCRIPTION OF MATERIAL \_\_\_\_\_

APPROXIMATE AMOUNT OF MATERIAL (SF) 120 (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR \_\_\_\_\_ CEILING

DESCRIPTION

APPROXIMATE AMOUNT OF MATERIAL \_\_\_\_\_ (SF) 120 (LF) \_\_\_\_\_

FRIABLE: \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_  
NON-FRIABLE \_\_\_\_\_ (YES)  (NO) \_\_\_\_\_  
WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO)   
CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO)

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL  WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED   
PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10%  10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
OVERALL RATING: GOOD  FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
DESCRIPTION: See

POTENTIAL FOR DISTURBANCE: ACCESSIBLE \_\_\_\_\_ INACCESSIBLE \_\_\_\_\_  
POTENTIAL FOR CONTACT: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW   
INFLUENCE OF VIBRATION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW   
POTENTIAL FOR AIR EROSION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW   
OVERALL RATING: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW

DESCRIPTION: Candidate for in-place operations and maintenance  
LOCATION IN AIR PLENUM: YES \_\_\_\_\_ NO \_\_\_\_\_  
Operations and Maintenance OK

INSPECTOR: Charles Spear ACCREDITATION NO. 100-21-24394  
SIGNATURE: Charles Spear DATE: 1/31/22

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Pauls H/S FLOOR MAIN  
FUNCTIONAL AREA Classes #24, HOMOGENEOUS MATERIAL 1' kn put tile

TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
FLOORING  CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
DESCRIPTION OF MATERIAL 1' kn put tile

APPROXIMATE AMOUNT OF MATERIAL (SF) 1000 (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR  CEILING \_\_\_\_\_

DESCRIPTION

APPROXIMATE AMOUNT OF MATERIAL \_\_\_\_\_ (SF) \_\_\_\_\_ (LF) \_\_\_\_\_  
FRIABLE: \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_

NON-FRIABLE \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_

WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_

CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL \_\_\_\_\_ WATER \_\_\_\_\_ FIRE \_\_\_\_\_

EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED

PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10%  10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_

OVERALL RATING: GOOD  FAIR \_\_\_\_\_ POOR \_\_\_\_\_

DESCRIPTION: etc

POTENTIAL FOR DISTURBANCE: ACCESSIBLE  INACCESSIBLE \_\_\_\_\_

POTENTIAL FOR CONTACT: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW

INFLUENCE OF VIBRATION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW

POTENTIAL FOR AIR EROSION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW

OVERALL RATING: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW

DESCRIPTION: Candidate for in-place operations and maintenance

LOCATION IN AIR PLENUM: YES \_\_\_\_\_ NO

Operations and Maintenance OKM

INSPECTOR: Charles Spear ACCREDITATION NO. IR0-21-24397

SIGNATURE: Charles Spear DATE: 11/3/76 msn

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING 2nd Lt H/4 FLOOR M A 111  
FUNCTIONAL AREA Stalls HOMOGENEOUS MATERIAL wooden material

TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
FLOORING \_\_\_\_\_ CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER X  
DESCRIPTION OF MATERIAL wooden material

APPROXIMATE AMOUNT OF MATERIAL (SF) \_\_\_\_\_ (LF) 71011

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC X FLOOR \_\_\_\_\_ CEILING \_\_\_\_\_

DESCRIPTION

APPROXIMATE AMOUNT OF MATERIAL (SF) \_\_\_\_\_ (LF) 71011

FRIABLE: \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_  
NON-FRIABLE \_\_\_\_\_ (YES) X (NO) \_\_\_\_\_  
WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) 2  
CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) 1

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL X WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED \_\_\_\_\_  
PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% X 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
OVERALL RATING: GOOD \_\_\_\_\_ FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
DESCRIPTION: O&M

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE \_\_\_\_\_  
POTENTIAL FOR CONTACT: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X  
INFLUENCE OF VIBRATION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW A  
POTENTIAL FOR AIR EROSION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X  
OVERALL RATING: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW \_\_\_\_\_

DESCRIPTION: Candidate for in-place operations and maintenance  
LOCATION IN AIR PLENUM: YES X NO \_\_\_\_\_  
Operations and Maintenance O&M

INSPECTOR: Charles Spear ACCREDITATION NO. IAA-21-24911  
SIGNATURE: Charles Spear DATE: 1/31/22 mm

APPENDIX 3.0

REGULATIONS



THIS IS TO CERTIFY THAT

**CHARLES SPEAR**

**HAS SUCCESSFULLY COMPLETED THE TRAINING COURSE**

for

**ONLINE AHERA ASBESTOS INSPECTOR REFRESHER**

In accordance with TSCA Title II, Part 763, Subpart E, Appendix C of 40 CFR

4-Hour Online AHERA Inspector Refresher  
Training; AHERA is the Asbestos Hazard  
Emergency Response Act enacting Title II of  
Toxic Substance Control Act (TSCA)

**Expiration Date:** 02/23/2022



Course Date: 02/23/2021

Course Location: Portland, OR

Certificate: IRO-21-2439A

For verification of the authenticity of this  
certificate contact  
PBS Engineering and Environmental Inc.  
4412 S Corbett Avenue  
Portland, Oregon 97239  
503.248.1939

A handwritten signature in black ink that reads "Andy Fridley".

Andy Fridley, Instructor

# Asbestos Survey Requirements

All commercial buildings regardless of construction date and residential buildings constructed before 2004 must have an asbestos survey conducted by an accredited inspector prior to any demolition or renovation activities. A copy of the asbestos survey report must be on-site during all renovation or demolition activities, and must be provided to DEQ upon request.

Owner occupants of a single family home performing their own home renovation project are exempt from the asbestos survey rule. However, DEQ recommends owner occupants have an asbestos survey performed or take samples of suspect materials and send to a lab for analysis prior to renovation projects even though it's not required. Owner occupants are required to follow all asbestos packaging, labeling and disposal requirements, and lab analysis is the only way to identify if asbestos is present in materials.

Demolition is defined as wrecking that involves the removal of any load-supporting component or intentional burning.

Renovation is defined as altering one or more building components that does not involve removing a load-supporting component. Renovation includes the replacement, stripping, or repair of building components, such as mechanical ventilation systems, pipes, ceilings, walls, flooring, and insulating materials.

**Who can perform the survey and produce the asbestos survey report?**  
Only an accredited AHERA inspector may perform the asbestos survey and produce an asbestos survey report.

For training courses, contact PBS Environmental Building Consultants at 503-248-1939 or Asbestos Training Project at 503-233-7707

**What does the survey involve?**  
DEQ generally requires a sample of each type of material suspected to contain asbestos to be collected and analyzed at a laboratory before any demolition or renovation activity.  
A complete demolition or extensive renovation is planned, an asbestos survey of the entire facility is required. When partial

An asbestos survey report includes all of the following:

- Dates the asbestos survey was performed
- A copy of the accredited inspectors certificate and their phone numbers
- The project site address and location where the survey was performed
- The facility owner or operator's name and phone
- Description of the facility, and area surveyed, including past and current use, area square footage, approximate construction date and number of floors
- The purpose of the asbestos survey
- Description of any limitation of the asbestos survey
- A table listing all of the materials sampled and identified as asbestos-containing or presumed asbestos-containing including the percent asbestos and type of asbestos, description of the material color, texture and pattern, the location of the material, description of the material condition as in good condition or in poor condition, identification of the material as friable or nonfriable and the approximate quantity of the material;
- A recommended response action
- A complete copy of the laboratory report including the laboratory name, address and phone number, unique sample analysis identification number, bulk sample analysis results, name of the analyst and the completed chain of custody for the samples.

renovation is planned, such as a kitchen remodel, a survey is required for that area of the structure only. If a single material, such as sheet vinyl flooring is to be removed, then an accredited inspector must take a sample of each layer of flooring and have it analyzed. Alternatively, the material can be presumed to contain asbestos, in which case it must be treated, removed, handled, managed, transported and disposed of as asbestos-containing material.

**Additional information**  
Visit [www.oregon.gov/deq/hazards-and-Cleanup/Pages/Asbestos-Information.aspx](http://www.oregon.gov/deq/hazards-and-Cleanup/Pages/Asbestos-Information.aspx)  
Find all DEQ's asbestos requirements in Administrative Rules 340, Division 248.

An asbestos survey may not be required if the project meets certain conditions. If you have



State of Oregon  
Department of  
Environmental  
Quality

Asbestos Program

Contact information:

Clackamas, Clatsop,  
Columbia, Multnomah,  
Tillamook and Washington  
Counties, call the  
Northwest Region –  
Portland Office at 503-  
229-5982, 503-229-5364 or  
800-452-4011.

Benton, Lincoln, Linn,  
Marion, Polk and Yamhill  
Counties, call the Western  
Region – Salem Office at  
503-378-5086 or 800-349-  
7677

Lackam, Josephine and  
Eastern Douglas Counties  
call the Western Region –  
Medford Office at 541-753-  
7747 or 877-832-1276.  
Clatsop, Curry and Western  
Oregon Counties – Coos  
Bay Office at 541-266-  
2711, ext. 222

Cook, Deschutes, Harney,  
Hood River, Jefferson,  
Klamath, Lake, Sherman  
and Wasco Counties, call  
the Eastern Region – Bend  
Office at 541-633-2019 or  
866-863-6668.  
Baker, Gilliam, Grant,  
Malheur, Morrow,  
Union, Wallowa  
and Wheeler Counties, call  
the Eastern Region –  
Pendleton Office at 541-  
278-4626 or 800-304-3313  
Lane County, call the Lane  
Regional Air Protection  
Agency at 541-736-1056.

Last Updated: 05/03/19  
By: Laura Gleim

questions or need technical assistance, contact asbestos program staff.

Contact a professional asbestos abatement contractor with any concerns about proper asbestos removal.

If asbestos-containing materials are disturbed or mishandled, the public and the environment may be exposed to asbestos fibers. Violations of asbestos rules and statutes may subject the property owner or operator or the contractor to civil penalties.


#### **Alternative formats**

DEQ can provide documents in an alternate format or in a language other than English upon request. Call DEQ at 800-452-4011 or email [deqinfo@deq.state.or.us](mailto:deqinfo@deq.state.or.us).

An official website of the United States government.

Close

We've made some changes to EPA.gov. If the information you are looking for is not here, you may be able to find it on the EPA Web Archive or the January 19, 2017 Web Snapshot.



## Asbestos and School Buildings

Public and non-profit private schools have distinct regulatory requirements to protect school children and school employees from asbestos exposure. This page provides information on these requirements as well as resource materials for schools and parents.

- [Learn Federal Requirements](#)
  - [How Schools Comply with the Asbestos Hazard Emergency Response Act \(AHERA\)](#)
  - [School Asbestos Management Plans](#)
- [Find Resources for Schools and Parents](#)
- [En Español, Información para padres, maestros y otros empleados escolares](#)

## Learn Federal Requirements

The [Asbestos Hazard Emergency Response Act \(AHERA\)](#) and its regulations require public school districts and non-profit schools including charter schools and schools affiliated with religious institutions to:

- Inspect their schools for asbestos-containing building material
- Prepare management plans and to take action to prevent or reduce asbestos hazards

These legal requirements are founded on the principle of "in-place" management of asbestos-containing material. Removal of these materials is not usually necessary unless the material is severely damaged or will be disturbed by a building demolition or renovation project.

Personnel working on asbestos activities in schools must be trained and accredited in accordance with [The Asbestos Model Accreditation Plan](#).

In addition, if removal of asbestos during renovation is warranted, or school buildings will be demolished, public school districts and non-profit schools must comply with the [Asbestos National Emissions Standards for Hazardous Air Pollutants \(NESHAP\)](#).

[Read more about NESHAP regulations for renovation and demolition of buildings.](#)

In addition, state and local agencies may have more stringent standards than those required by the Federal government.



## How Schools Comply with the Asbestos Hazard Emergency Response Act (AHERA)

The [AHERA regulations](#) require public school districts and non-profit schools to:

- Perform an original inspection to determine whether asbestos-containing materials are present and then re-inspect asbestos-containing material in each school every three years
- Develop, maintain, and update an [asbestos management plan](#) and keep a copy at the school
- Provide yearly notification to parent, teacher, and employee organizations on the availability of the school's asbestos management plan and any asbestos-related actions taken or planned in the school
- Designate a contact person to ensure the responsibilities of the public school district or the non-profit school are properly implemented
- Perform periodic surveillance of known or suspected asbestos-containing building material
- Ensure that trained and licensed professionals perform inspections and take response actions
- Provide custodial staff with asbestos-awareness training

### School Asbestos Management Plans

Public school districts and non-profit schools are required to develop, maintain and update asbestos management plans and to keep a copy at each individual schools. These plans are required to document the recommended asbestos response actions, the location of the asbestos within the school, and any action taken to repair and remove the material.

The school authority must maintain records to be included in the Asbestos Management Plan. These records, among other things, include:

- Name and address of each school building and whether the building has asbestos-containing building material, and the type of asbestos-containing material
- Date of the original school inspection
- Plan for re-inspections
- Blueprint that clearly identifies the location of asbestos-containing building materials that remains in the school
- Description of any response action or preventive measures taken to reduce asbestos exposure
- Copy of the analysis of any building, and the name and address of any laboratory that sampled the material
- Name, address, and telephone number of the “designated person” or contact to ensure the duties of the school district or non-profit private school are carried out
- Description of steps taken to inform workers, teachers, and students or their legal guardians about inspections, re-inspections, response actions, and periodic surveillance

Parents, teachers, and school employees, or their representatives, have the right to inspect the school’s asbestos management plan. Schools are required to notify parent-teacher organizations (such as PTAs) once a year about the availability of the school’s asbestos management plan and asbestos-related activity taking place within the school. The school must make the plan available for inspection within five working days of it being requested.

For a complete list of School Asbestos Management Plan Requirements, see the [Asbestos-Containing Materials in Schools Rule](#).

## Find Resources for Schools and Parents

- [How to Manage Asbestos in School Buildings: The AHERA Designated Person's Self-Study Guide \(January 1996\)](#)
- [AHERA Asbestos Management Plan Self-Audit Checklist for Designated Persons \(February 2009\)](#)
- [Model AHERA Asbestos Management Plan for Local Education Agencies \(February 2009\)](#)
- [The ABC's of Asbestos in Schools \(August 2003\)](#)
- [Asbestos in Schools Fact Sheet \(August 2003\)](#)
- [EPA's Creating Healthy Indoor Environments in Schools Website](#)
- [What Local Education Agencies \(LEAs\) Should Know About the National Emission Standard for Hazardous Air Pollutants \(NESHAP\) \(March 2005\)](#)
- [Find Labs for Testing Asbestos](#)
- [Find frequent questions on schools](#)

## En Español, Información para parientes, maestros y otros empleados escolares

- [El ABC del Asbesto en las Escuelas](#)
- [Plan de manejo de asbesto de AHERA, Lista de comprobación de auditoría interna para Personas designadas](#)
- [Modelo AHERA para el Plan de manejo de asbesto para las Agencias locales de educación](#)

LAST UPDATED ON JUNE 14, 2018