



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>

cinnaminsonradonlab@emsl.com

EMSL Order: 382210131

CustomerID: INDS42

CustomerPO:

ProjectID:

Attn: **Elessar Connolly-Fairchild**
Indy Safety
5010 NE Roselawn St
Portland, OR 97218

Phone: (503) 501-7396
Fax:
Received: 12/12/2022 02:02 PM
Analysis Date: 12/13/2022
Collected: 12/6/2022

Project: **Banks School District High School**

Banks School District High School

Test Report: Radon in Air Test Results

Liquid Scintillation ID	Location	Radon Activity (pCi/L)	Start	Stop	Temperature F	Humidity %	Sample Type
515163 382210131-0001	Rm 1	1.8	12/6/2022 3:45:00 PM	12/8/2022 4:15:00 PM	68	49	Customer
Sample Notes:							
517598 382210131-0002	Rm 3		12/6/2022 3:49:00 PM	12/8/2022 4:15:00 PM	68	49	Customer
Sample Notes: Not Analyzed Radon device not received by lab.							
521095 382210131-0003	Rm 4	0.5	12/6/2022 3:50:00 PM	12/8/2022 4:17:00 PM	70	48	Customer
Sample Notes:							
517867 382210131-0004	Rm 5	0.5	12/6/2022 3:53:00 PM	12/8/2022 4:18:00 PM	70	46	Customer
Sample Notes:							
518637 382210131-0005	Rm 6	0.4	12/6/2022 3:54:00 PM	12/8/2022 4:19:00 PM	71	46	Customer
Sample Notes:							
507438 382210131-0006	Rm 7	0.5	12/6/2022 3:58:00 PM	12/8/2022 4:20:00 PM	71	46	Customer
Sample Notes:							
515200 382210131-0007	Rm 9	0.4	12/6/2022 4:00:00 PM	12/8/2022 4:23:00 PM	72	45	Customer
Sample Notes:							
517577 382210131-0008	Rm 8 1	0.5	12/6/2022 4:02:00 PM	12/8/2022 4:24:00 PM	72	45	Customer
Sample Notes:							
521024 382210131-0009	Rm 8 2	0.2	12/6/2022 4:03:00 PM	12/8/2022 4:26:00 PM	72	45	Customer
Sample Notes:							
517814 382210131-0010	Lib Work Rm	0.5	12/6/2022 4:06:00 PM	12/8/2022 4:26:00 PM	73	43	Customer
Sample Notes:							

Please visit www.radontestinglab.com



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order:	382210131
CustomerID:	INDS42
CustomerPO:	
ProjectID:	

Test Report: Radon in Air Test Results

Liquid Scintillation ID	Location	Radon Activity (pCi/L)	Start	Stop	Temperature F	Humidity %	Sample Type
520414 382210131-0011	Lib Work Rm D	0.5	12/6/2022 4:06:00 PM	12/8/2022 4:26:00 PM	73	43	Duplicate
Sample Notes: Duplicate's Customer Sample:382210131-0010							Duplicate RPD = 0.0%
520594 382210131-0012	Lib Work Rm Office	0.7	12/6/2022 4:07:00 PM	12/8/2022 4:27:00 PM	73	43	Customer
Sample Notes:							
517817 382210131-0013	Rm 10 Office	0.5	12/6/2022 4:10:00 PM	12/8/2022 4:30:00 PM	72	44	Customer
Sample Notes:							
517643 382210131-0014	Rm 10 1	0.5	12/6/2022 4:10:00 PM	12/8/2022 4:28:00 PM	73	42	Customer
Sample Notes:							
517860 382210131-0015	Rm 10 2	0.5	12/6/2022 4:11:00 PM	12/8/2022 4:29:00 PM	73	42	Customer
Sample Notes:							
517812 382210131-0016	Cafeteria		12/6/2022 4:15:00 PM	12/8/2022 4:29:00 PM	73	42	Customer
Sample Notes: Not Analyzed Radon device not received by lab.							
517861 382210131-0017	Café Staff	0.5	12/6/2022 4:16:00 PM	12/8/2022 4:32:00 PM	73	43	Customer
Sample Notes:							
517676 382210131-0018	Staff Break Rm	0.9	12/6/2022 4:18:00 PM	12/8/2022 4:34:00 PM	73	47	Customer
Sample Notes:							
520411 382210131-0019	Rm 11D	0.5	12/6/2022 4:20:00 PM	12/8/2022 4:35:00 PM	72	49	Customer
Sample Notes:							
520995 382210131-0020	Kitchen Office	0.8	12/6/2022 4:27:00 PM	12/8/2022 4:36:00 PM	67	46	Customer
Sample Notes:							
521025 382210131-0021	Rm 12	0.5	12/6/2022 4:30:00 PM	12/8/2022 4:38:00 PM	71	46	Customer
Sample Notes:							
517666 382210131-0022	Rm 12 D	0.3	12/6/2022 4:30:00 PM	12/8/2022 4:38:00 PM	71	46	Duplicate
Sample Notes: Duplicate's Customer Sample:382210131-0021							Duplicate RPD = 50.0%
517850 382210131-0023	Gym SE	1.3	12/6/2022 4:36:00 PM	12/8/2022 4:40:00 PM	72	48	Customer
Sample Notes:							

Please visit www.radontestinglab.com



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>

cinnaminsonradonlab@emsl.com

EMSL Order:	382210131
CustomerID:	INDS42
CustomerPO:	
ProjectID:	

Test Report: Radon in Air Test Results

Liquid Scintillation ID	Location	Radon Activity (pCi/L)	Start	Stop	Temperature F	Humidity %	Sample Type
517657 382210131-0024	Gym SE		12/6/2022 4:42:00 PM	12/8/2022 4:40:00 PM	72	48	Customer
Sample Notes: Not Analyzed Radon device not received by lab.							
519775 382210131-0025	Girls Coach Office	3	12/6/2022 4:48:00 PM	12/8/2022 4:41:00 PM	66	46	Customer
Sample Notes: Radon device exposed <48 hours							
517884 382210131-0026	Boys Coach Office	5.3	12/6/2022 4:45:00 PM	12/8/2022 4:47:00 PM	68	47	Customer
Sample Notes:							
515364 382210131-0027	Rm 16 Main		12/6/2022 4:47:00 PM	12/8/2022 4:47:00 PM	68	47	Customer
Sample Notes: Not Analyzed Radon device not received by lab.							
517873 382210131-0028	Rm 16D	0.3	12/6/2022 4:49:00 PM	12/8/2022 4:54:00 PM	69	47	Customer
Sample Notes:							
517809 382210131-0029	Rm 16B	0.8	12/6/2022 4:52:00 PM	12/8/2022 4:55:00 PM	70	46	Customer
Sample Notes:							
507535 382210131-0030	Rm 16A	0.7	12/6/2022 4:53:00 PM	12/8/2022 4:56:00 PM	70	45	Customer
Sample Notes:							
521091 382210131-0031	Rm 17	0.4	12/6/2022 4:55:00 PM	12/8/2022 4:57:00 PM	71	46	Customer
Sample Notes:							
517560 382210131-0032	Rm 18N	1.2	12/6/2022 5:02:00 PM	12/8/2022 5:03:00 PM	72	45	Customer
Sample Notes:							
507476 382210131-0033	Rm 18N D	0.9	12/6/2022 5:02:00 PM	12/8/2022 5:03:00 PM	72	45	Duplicate
Sample Notes: Duplicate's Customer Sample:382210131-0032							
Duplicate RPD = 28.6%							
521083 382210131-0034	Rm 18S	0.7	12/6/2022 5:04:00 PM	12/8/2022 5:04:00 PM	72	44	Customer
Sample Notes:							
517875 382210131-0035	Consessions	1.7	12/6/2022 5:06:00 PM	12/8/2022 5:06:00 PM	71	46	Customer
Sample Notes:							
507495 382210131-0036	Rm 19	0.3	12/6/2022 5:12:00 PM	12/8/2022 5:13:00 PM	71	45	Customer
Sample Notes:							

Please visit www.radontestinglab.com



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>

cinnaminsonradonlab@emsl.com

EMSL Order: 382210131

CustomerID: INDS42

CustomerPO:

ProjectID:

Test Report: Radon in Air Test Results

Liquid Scintillation ID	Location	Radon Activity (pCi/L)	Start	Stop	Temperature F	Humidity %	Sample Type
507423 382210131-0037	Rm 20	0.7	12/6/2022 5:14:00 PM	12/8/2022 5:14:00 PM	71	44	Customer
Sample Notes:							
517913 382210131-0038	Rm 22	0.7	12/6/2022 5:17:00 PM	12/8/2022 5:17:00 PM	71	43	Customer
Sample Notes:							
507480 382210131-0039	Rm 24	0.9	12/6/2022 5:19:00 PM	12/8/2022 5:26:00 PM	73	43	Customer
Sample Notes:							
507633 382210131-0040	Rm 23	0.3	12/6/2022 5:19:00 PM	12/8/2022 5:29:00 PM	73	41	Customer
Sample Notes:							
507421 382210131-0041	Rm 26	0.6	12/6/2022 5:22:00 PM	12/8/2022 5:31:00 PM	73	42	Customer
Sample Notes:							
507505 382210131-0042	Rm 26B	0.2	12/6/2022 5:23:00 PM	12/8/2022 5:31:00 PM	73	40	Customer
Sample Notes:							
507504 382210131-0043	Rm 26 Office	0.4	12/6/2022 5:26:00 PM	12/8/2022 5:32:00 PM	73	41	Customer
Sample Notes:							
507541 382210131-0044	Rm 26 Office D	0.2	12/6/2022 5:26:00 PM	12/8/2022 5:32:00 PM	73	41	Duplicate
Sample Notes: Duplicate's Customer Sample:382210131-0043						Duplicate RPD = 66.7%	
519776 382210131-0045	Rm 25	-0.1	12/6/2022 5:28:00 PM	12/8/2022 5:33:00 PM	73	41	Customer
Sample Notes:							
507527 382210131-0046	Rm 27	0.2	12/6/2022 5:31:00 PM	12/8/2022 5:35:00 PM	73	41	Customer
Sample Notes:							
520437 382210131-0047	Wood Shop Mid	0.9	12/6/2022 5:35:00 PM	12/8/2022 5:40:00 PM	71	40	Customer
Sample Notes:							
507531 382210131-0048	Metal Shop	0.7	12/6/2022 5:37:00 PM	12/8/2022 5:43:00 PM	70	41	Customer
Sample Notes:							
507496 382210131-0049	Rm 30	1.6	12/6/2022 5:40:00 PM	12/8/2022 5:44:00 PM	70	40	Customer
Sample Notes:							

Please visit www.radontestinglab.com



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>

cinnaminsonradonlab@emsl.com

EMSL Order: 382210131

CustomerID: INDS42

CustomerPO:

ProjectID:

Test Report: Radon in Air Test Results

Liquid Scintillation ID	Location	Radon Activity (pCi/L)	Start	Stop	Temperature F	Humidity %	Sample Type
521028 382210131-0050	Rm 31B	1.2	12/6/2022 5:41:00 PM	12/8/2022 5:47:00 PM	71	41	Customer
Sample Notes:							
507470 382210131-0051	Rm 31A	1.6	12/6/2022 5:43:00 PM	12/8/2022 5:48:00 PM	71	42	Customer
Sample Notes:							
517827 382210131-0052	Rm 31	1.5	12/6/2022 5:44:00 PM	12/8/2022 5:49:00 PM	71	40	Customer
Sample Notes:							
507501 382210131-0053	Office Lobby	1.3	12/6/2022 5:47:00 PM	12/8/2022 5:53:00 PM	70	45	Customer
Sample Notes:							
507544 382210131-0054	Rm 32A	2.3	12/6/2022 5:49:00 PM	12/8/2022 5:56:00 PM	71	44	Customer
Sample Notes:							
520413 382210131-0055	Rm 32B	2	12/6/2022 5:56:00 PM	12/8/2022 5:58:00 PM	71	44	Customer
Sample Notes:							
507512 382210131-0056	Rm 32B	1.6	12/6/2022 5:56:00 PM	12/8/2022 5:58:00 PM	71	44	Customer
Sample Notes:							
507410 382210131-0057	Rm 32C	2.5	12/6/2022 5:58:00 PM	12/8/2022 6:01:00 PM	71	45	Customer
Sample Notes:							
507546 382210131-0058	Rm 32D		12/6/2022 5:59:00 PM	12/8/2022 6:01:00 PM	71	45	Customer
Sample Notes: Not Analyzed Radon device not received by lab.							
507425 382210131-0059	Rm 32E	1.5	12/6/2022 6:01:00 PM	12/8/2022 6:03:00 PM	70	45	Customer
Sample Notes:							
507516 382210131-0060	Rm 32H	1.8	12/6/2022 6:03:00 PM	12/8/2022 6:04:00 PM	70	47	Customer
Sample Notes:							
507422 382210131-0061	Rm 32F	1.3	12/6/2022 6:05:00 PM	12/8/2022 6:08:00 PM	71	45	Customer
Sample Notes:							
520518 382210131-0062	Rm 32G	1.7	12/6/2022 6:08:00 PM	12/8/2022 6:09:00 PM	71	45	Customer
Sample Notes:							

Please visit www.radontestinglab.com



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>

cinnaminsonradonlab@emsl.com

EMSL Order: 382210131

CustomerID: INDS42

CustomerPO:

ProjectID:

Test Report: Radon in Air Test Results

Liquid Scintillation ID	Location	Radon Activity (pCi/L)	Start	Stop	Temperature F	Humidity %	Sample Type
517686 382210131-0063	Wrest N	1.3	12/6/2022 6:29:00 PM	12/8/2022 6:54:00 PM	61	74	Customer
Sample Notes: Humidity changed due to calibration factor.							
517911 382210131-0064	Wrest Office	1.1	12/6/2022 6:30:00 PM	12/8/2022 6:57:00 PM	65	74	Customer
Sample Notes: Humidity changed due to calibration factor.							
507452 382210131-0065	Wrest S	0.6	12/6/2022 6:31:00 PM	12/8/2022 6:56:00 PM	66	74	Customer
Sample Notes: Humidity changed due to calibration factor.							
517698 382210131-0066	Blank	0.2	12/6/2022 6:08:00 PM	12/8/2022 6:09:00 PM	70	45	Blank
Sample Notes:							
517958 382210131-0067	Blank	0.2	12/6/2022 6:08:00 PM	12/8/2022 6:09:00 PM	70	45	Blank
Sample Notes:							
517822 382210131-0068	Blank	0	12/6/2022 6:08:00 PM	12/8/2022 6:09:00 PM	70	45	Blank
Sample Notes:							
507523 382210131-0069	HS Office 106	39.4	12/3/2022 8:33:00 AM	12/5/2022 8:33:00 AM	70	50	Customer
Sample Notes:							
507420 382210131-0070	HS Office 107	44.4	12/3/2022 8:33:00 AM	12/5/2022 8:33:00 AM	70	50	Customer
Sample Notes:							
507402 382210131-0071	HS Office 108	43.3	12/3/2022 8:33:00 AM	12/5/2022 8:33:00 AM	70	50	Customer
Sample Notes:							
507508 382210131-0072	HS Office 109	38.9	12/3/2022 8:33:00 AM	12/5/2022 8:33:00 AM	70	50	Customer
Sample Notes:							

Report Notes

Please visit www.radontestinglab.com



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>

cinnaminsonradonlab@emsl.com

EMSL Order:	382210131
CustomerID:	INDS42
CustomerPO:	
ProjectID:	

Test Report: Radon in Air Test Results

Liquid Scintillation ID	Location	Radon Activity (pCi/L)	Start	Stop	Temperature F	Humidity %	Sample Type
-------------------------	----------	------------------------	-------	------	---------------	------------	-------------

The United States Environmental Protection Agency (EPA) has established a radon action level of 4.0pCi/L. EPA recommends mitigation of a structure if the confirmed radon level is equal to or greater than 4.0pCi/L.

The radon tests were performed using liquid scintillation radon detectors and counted on a liquid scintillation counter following EPA Method # 402-R-92-004 testing protocol for Radon in Air testing. EPA recommends retesting every two years.

Please contact EMSL Analytical, Inc. or your State Health Department for further information.

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of Radon in Air.

Analyst(s)

Dominic Gehret (67)

Dominic Gehret, Radiochemistry Laboratory Manager, NJ Radon Measurement Specialist MES 13910 or other approved signatory

In no event shall EMSL be liable for indirect, special, consequential, or incidental damages, including, but not limited to, damages for loss of profit or goodwill regardless of the negligence (either sole or concurrent) of EMSL and whether EMSL has been informed of the possibility of such damages, arising out of or in connection with EMSL's services thereunder or the delivery, use, reliance upon or interpretation of test results by client or any third party. We accept no legal responsibility for the purposes for which the client uses the test results. In no event shall EMSL be liable to a client or any third party, whether based upon theories of tort, contract or any other legal or equitable theory, in excess of the amount paid to EMSL by client thereunder. The test results meets all NELAC requirements unless otherwise specified.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ FL RB2034/R2687,IL RNL2008202,IN RTL00935,IA RNLAB10005,KS KS-LB-0005/KS-MS-0482,ME SPC202,MN RL-0005,NE 474/RMB-1083,NJ 03036/MEB92525/MES13910,NY 10872,OH RL39,OK D9952,PA 2573/3393/68-00367,RI RMB-108/RI00179,WV RL000220,NRSB-ARL6006,NRPP

Initial report from 12/15/2022 11:07:38